

6	Tyler	1	WV	74	WV 74	Slip Repairs @ MP 0.10, 0.20, 0.40, 0.65 . Needs ditched, paved and culvert replacements from MP 0.00-1.96. Heavy Truck
6	Tyler	2	WV	180	WV 180	Needs paved and ditched MP 0.00-4.06. Heavy Truck Hauling Route.
6	Tyler	3	WV	2	WV 2	Needs ditched and paved from MP 0.00-9.08 and MP 10.24-13.12.
6	Tyler	4	CO	40	Big Run	Slip Repairs @ MP 1.10, 1.90, 2.60, 2.90, 3.10, 4.40. Road needs ditched, paved and culvert replacements from MP 0.00-5.15.
6	Tyler	5	WV	18	WV 18	Slip Repairs @ MP 0.34, 16.32, 20.30, 21.34, 22.30. Needs paved, ditched and culvert replacement from MP 0.00-18.32
6	Tyler	6	CO	34	Gorrells Run	Slip Repair @ MP 2.30, 2.80, 3.80. Road needs milled and paved from MP 0.00-0.40. Road needs ditched, paved and culvert
6	Tyler	7	CO	10/1	Allen Run	Large culvert replacement.
6	Tyler	8	CO	10	Adonis/Sellers	Slip Repair @ MP 4.90. Road needs ditched, paved and culvert replacements from MP 0.00-2.87.
6	Tyler	9	CO	10/1	Sellers Road	Road needs ditched, paved and culvert replacements from MP 0.00-3.87.
6	Tyler	10	CO	1/4	Gamble Run	Road needs ditched, paved and culvert replacements from MP 0.00-0.99 & MP 1.60-2.71.
6	Tyler	11	CO	5	Arvilla	Road needs ditched, paved and culvert replacements from MP 0.00-0.98.
6	Tyler	12	CO	50	Ross Run	Underwood Bridge Replacement MP 0.45
6	Tyler	13	CO	13/1	Walnut Fork	Road needs ditched, paved and culvert replacements from MP 0.00-2.41.
6	Tyler	14	CO	1	Buck Run	Slip Repairs @ MP 5.04, 5.05, 5.24, 5.34, 5.54, 5.64, 5.74, 5.84, 5.94, 5.99, 6.14, 6.74, 6.84, 6.94, 7.04. Road needs ditched,
6	Tyler	15	CO	11	Elk Fork	Slip Repairs MP 1.26, 3.20, 7.20, 9.80. Needs ditched, paved and culvert replacements from MP 8.60-10.24.
6	Tyler	16	CO	15	Jacksonburg Hill	Road needs ditched, paved and culvert replacements from MP 0.00-1.15.
6	Tyler	17	CO	13	Indian Creek	Slip Repair @ MP 1.50. Road needs ditched, paved and culvert replacements from MP 9.18-12.09.
6	Tyler	18	CO	28/1	Wetzel/Tyler Ridge	Slip Repairs @ MP 3.45, 5.95, 7.00, 7.53, 7.76, 7.79, 7.82. Road needs ditched, paved and culvert replacements from MP 7.60-
6	Tyler	19	WV	23	WV 23	Slip Repairs @ MP 1.30, 2.00, 7.09. Needs ditched, paved and culvert replacements from MP 0.00-8.75. Heavy Truck Hauling
6	Tyler	20	CO	24	Sellers Road	Slip Repairs @ MP 0.60, 0.70, 2.00, 2.10, 2.20, 2.30.
6	Tyler	21	CO	18/7	Pitts Lane	Large culvert replacement.

6	Tyler	22	CO	18/2	Badger Run	Slip Repairs @ MP 0.60, 0.70, 1.40. Road needs ditched, paved and culvert replacements from MP 0.00-1.67.
6	Tyler	23	CO	18/5	Dry Run	Slip Repairs @ MP 1.20 & 1.62. Road needs ditched, paved and culvert replacements from MP 0.00-2.40.
6	Tyler	24	CO	12	Next Road	Slip Repair @ MP 1.45. Road needs ditched, paved and culvert replacements from MP 0.00-1.66
6	Tyler	25	CO	32	Ten Mile	Ten Mile Bridge Replacement MP 0.05
6	Tyler	26	CO	18/4	Pleasant Ridge	Slip Repair @ MP 2.90. Road needs ditched, paved and culvert replacements from MP 2.38-3.50.
6	Tyler	27	CO	6	Rush Fork	Slip Repair @ MP 6.88. Road needs ditched, paved and culvert replacements from MP 3.53-7.52.
6	Tyler	28	CO	3	Cowhouse	Road needs ditched, paved and culvert replacements from MP 0.00-3.97.
6	Tyler	29	CO	10/2	Stewarts Run	Slip Repair @ MP 0.30. Road needs ditched, paved and culvert replacements from MP 0.00-1.98.
6	Tyler	30	CO	6/3	Little Sancho	Slip Repair @ MP 0.35. Road needs ditched, paved and culvert replacements from MP 0.00-3.67.
6	Tyler	31	CO	1/6	Slider Run	Road needs ditched, paved and culvert replacements from MP 0.00-1.00 and MP 2.57-3.78.
6	Tyler	32	WV	23	Davis Run Bridge	Davis Run bridge replacement MP 7.46
6	Tyler	33	CO	7/4	Twin Hickories	Short Span Bridge Replacement MP 2.56
6	Tyler	34	CO	18/1	McCoach's Lane	Road needs ditched, paved and culvert replacements from MP 0.00-1.31.
6	Tyler	35	CO	13/4	McIntyre Fork	Road needs ditched, paved and culvert replacements from MP 0.00-2.03.
6	Tyler	36	CO	8/1	Rippentuck	Large culvert replacement.
6	Tyler	37	CO	24/2	Golding	Slip Repair @ MP 0.40.
6	Tyler	38	CO	11		Leasure Chapel Bridge Replacement MP 0.04
6	Tyler	39	CO	7	Wick	Short Span Bridge Replacement MP 7.40.
6	Tyler	40	CO	7/6	Wheeler's Run	Road needs ditched, paved and culvert replacements from MP 0.00-0.90.
6	Tyler	41	CO	7/3	Rock Run	Slip Repairs @ MP 1.91 & 1.94.
6	Tyler	42	CO	2/4	Wells Hill	Slip Repairs @ MP 0.32 & 0.41.

6	Tyler	43	CO	18/18	Smith Ridge	Road needs ditched, paved and culvert replacements from MP 0.00-0.74.
6	Tyler	44	CO	56	Deep Valley	Deep Valley Bridge Replacement MP 0.20
6	Tyler	45	CO	40/1	Meeker	Big Run Bridge Replacement MP 0.01.
6	Tyler	46	CO	18/22	Pleasant View Lane	Road needs ditched and paved from MP 0.00-0.18.
6	Tyler	47	CO	18/25 & 18/20	Silver Knight Circle	Road needs ditched and paved from MP 0.00-0.20.
6	Tyler	48	CO	2/8	Sistersville School	Road needs ditched and paved from MP 0.00-0.23.
6	Tyler	49	CO	18/6	State Ridge	Slip Repairs @ MP 2.10 & 3.28.
6	Tyler	50	CO	18/11	Old WV 18	Slip Repairs @ MP 1.44 & 1.74.
6	Tyler	51	CO	14/4	Slickers Falls	Slip Repair @ MP 3.00.
6	Tyler	52	CO	56/4	Todd Hollow	Slip Repair @ MP 0.15.
6	Tyler	53	CO	6/5	Brush Run	Brush Run Bridge Replacement MP 1.34.
6	Tyler	54	CO	13	Indian Creek	Short Span Bridge Replacement MP 9.60.
6	Wetzel	1	US	250	US 250	Slip Repairs @ MP 0.77, 7.09, 7.20, 7.24, 7.90, 9.50, 9.62, 10.40, 10.60, 10.77. Needs Paved MP 3.26-4.38. Base Failure Repair
6	Wetzel	2	WV	20	WV 20	Slip Repairs @ MP 9.60, 14.60, 15.24, 19.39, 26.58, 26.68, 28.40, 29.20. Needs paved and ditched MP 11.74-15.23. MP
6	Wetzel	3	CO	50	Furbee Ridge	Slip Repairs @ MP 0.90, 1.00, 1.40. Needs paved, ditched and culverts replaced MP 0.00 - 3.30.
6	Wetzel	4	WV	69	WV 69	Slip Repairs @ MP 1.40, 1.46, 1.50. Needs milled And paved from MP 0.00-0.20. Needs paved and ditched from MP 0.20-
6	Wetzel	5	CO	5	Limestone Ridge	Slip Repair @ MP 0.93. Needs paved, ditched and culverts replaced MP 0.00-3.43.
6	Wetzel	6	CO	3	Doolin	Slip Repair @ MP 0.20, 5.50, 5.52, 5.83, 7.60, 7.90, 8.07, 8.94, 9.40, 9.46, 9.74, 9.76, 10.05, 10.33, 10.40. Road needs ditched,
6	Wetzel	7	CO	12	Long Drain	Needs paved, ditched and culverts replaced MP 0.00-3.67.
6	Wetzel	8	WV	7	WV 7	Slip Repairs @ MP 6.09, 7.08, 7.43, 25.79, 27.00, 27.60, 29.20, 30.20, 30.22, 30.26. Base Failure Repair in spots MP 15.00-
6	Wetzel	9	WV	180	WV 180	Road needs ditched and paved from MP 0.00-3.33.

6	Wetzel	10	CO	89	Old WV 89	Slip Repairs @ MP 2.30, 4.21, 4.30, 4.32, 6.59, 9.38, 9.50, 10.30, 13.24, 13.34, 14.74, 14.84, 14.85, 16.80, 17.18.
6	Wetzel	11	CO	7/5	Hog Run Bridge	Bridge Replacement @ MP 0.02.
6	Wetzel	12	CO	3/1	American Ridge	Slip Repairs @ MP 1.70, 1.90, 2.20. Needs paved, ditched and culverts replaced MP 0.00-2.61.
6	Wetzel	13	CO	8	Low Gap	Slip Repairs @ MP 0.70, 3.10, 3.20, 3.30, 4.10, 4.70, 4.73, 5.30. Road needs ditched and culvert replacements. EQI has already
6	Wetzel	14	CO	2/1	Whiskey Run	Slip Repair @ MP 0.10. Road needs ditched, paved and culvert replacements from MP 0.00-1.54.
6	Wetzel	15	CO	21	Mannington	Road needs ditched, paved and culvert replacements from MP 0.00-5.26.
6	Wetzel	16	CO	9	Sugar Run	Road needs ditched, paved and culvert replacements from MP 2.00-4.56.
6	Wetzel	17	CO	17	Barker Hill	Slip Repair @ MP 3.15. Road needs ditched, paved and culvert replacements from MP 0.00-3.69.
6	Wetzel	18	CO	26/2	Gamble Run	Needs paved, ditched and culverts replaced MP 0.00-0.48.
6	Wetzel	19	CO	64	Earnshaw-Wiley Fork	Slip Repair @ MP 2.80. Road needs ditched, paved and culvert replacements from MP 2.39-4.96.
6	Wetzel	20	CO	30	Whiteman Hill	Slip Repair @ MP 0.90 & 2.80. Road needs ditched, paved and culvert replacements from MP 0.00-2.89.
6	Wetzel	21	WV	7	Cook Bridge	Bridge Replacement @ MP 11.58.
6	Wetzel	22	CO	11	Church Fork	Slip Repair @ MP 2.90 & 3.10. Road needs ditched, paved and culvert replacements from MP 0.00-3.18.
6	Wetzel	23	CO	7/8	Postlewait Ridge	Slip Repair @ MP 2.80. Road needs ditched, paved and culvert replacements from MP 0.00-3.86.
6	Wetzel	24	CO	20/1	Chiselfinger	Slip Repair @ MP 1.20 & 1.50. Road needs ditched, paved and culvert replacements from MP 0.00-3.73.
6	Wetzel	25	CO	22	Schnupach Ridge	Slip Repair @ MP 0.10 & 3.55. Road needs ditched, paved and culvert replacements from MP 0.0-3.15.
6	Wetzel	26	CO	14	Browns Run	Slip Repair @ MP 2.30. Road needs ditched, paved and culvert replacements from MP 1.00-2.44.
6	Wetzel	27	CO	16/1	Plants Hill	Slip Repair @ MP 0.50. Road needs ditched, paved and culvert replacements from MP 0.00-2.25.
6	Wetzel	28	CO	8/3	Morris Run	Slip Repair @ MP 0.10. Road needs ditched, paved and culvert replacements from MP 0.00-2.22.
6	Wetzel	29	CO	10	Lemley Ridge	Road needs ditched, paved and culvert replacements from MP 0.00-2.22.
6	Wetzel	30	WV	7	Richard Snyder Memorial Bridge	Bridge Replacement @ MP 0.07.

6	Wetzel	31	CO	20/5	Trader Fork	Slip Repair @ MP 0.40.
6	Wetzel	32	CO	42	Money Run	Slip Repairs @ MP 0.70, 0.80, 0.90, 1.30.
6	Wetzel	33	CO	6	Macedonia Ridge	Slip Repairs @ MP 0.77, 0.80, 2.37.
6	Wetzel	34	CO	24	Fairview Ridge	Slip repair @ MP 2.97, 3.30, 4.60. Road needs culvert replacements.
6	Wetzel	35	CO	250/3	Santee Run	Road needs ditched, paved and culvert replacements from MP 0.00-1.64.
6	Wetzel	36	CO	69/1	Round Bottom	Road needs ditched, paved and culvert replacements from MP 0.00-1.20.
6	Wetzel	37	CO	7/12	Kodol	Road needs ditched, paved and culvert replacements from MP 1.36-2.57.
6	Wetzel	38	CO	11/1	Hostutler Run	Road needs ditched, paved and culvert replacements from MP 0.00-1.16.
6	Wetzel	39	CO	11/2	Butcher Hollow	Road needs ditched, paved and culvert replacements from MP 0.00-1.14.
6	Wetzel	40	CO	7/22	Ashcamp Run	Road needs ditched, paved and culvert replacements from MP 0.00-0.93.
6	Wetzel	41	WV	20	Remmers Bridge	Bridge Replacement @ MP 10.83.
6	Wetzel	42	CO	1/6	Palmer Ridge	Slip Repairs @ MP 0.36 & 1.70.
6	Wetzel	43	CO	28/1	Cider Run	Slip Repair @ MP 0.31 & 0.40.
6	Wetzel	44	CO	58	Hoyt Ridge	Slip Repairs @ MP 1.20 & 5.90.
6	Wetzel	45	WV	7	Scheidler Run Bridge	Bridge Replacement @ MP 15.22.
6	Wetzel	46	WV	20	Folsom Bridge East	Bridge Replacement @ MP 1.46.
6	Wetzel	47	CO	13	Rush Run	Slip Repair @ MP 3.40.
6	Wetzel	48	CO	7/14	Robinson Ridge	Slip Repair @ MP 0.20.
6	Wetzel	49	CO	7/24	Delta Road	Slip Repair @ MP 0.46
6	Wetzel	50	CO	4/7	Hawkey Hill	Slip Repair @ MP 1.38.
6	Wetzel	51	CO	4	St. Josephs	Short Span Bridge Replacement @ MP 1.30.